

# OptiFlex 2 GM03

CONCERNING THE 1007217=(2) 1007986 SCREWS NEEDED TO ASSEMBLE



# OptiFlex 2 GM03 manual powder gun

OptiFlex 2 GM03 manual powder gun - complete: Gun, cable nozzles	1008 070
negative polarity, gun cable 2 m	1007 971
positive polarity, gun cable 2 m	1007 974
negative polarity, gun cable 6 m	1007 972
positive polarity, gun cable 6 m	1007 975
negative polarity, gun cable 12 m	1007 973
positive polarity, gun cable 12 m	1007 968
1 Gun body	1007 220
2 Cascade - complete, negative polarity	1007 231
Cascade - complete, positive polarity 90 % of guns are negative	1007 232
3 Print holder - complete	1007216
4 End plate with hook	1007217
5 Grip end plate - complete	1007961
6 Trigger - complete	1007213
7 Trigger cover	1007212
8 Countersunk-head screw - M4x6 mm	1000845
9 SuperCorona holder	1007238
10 Gun cable 2 m - complete	1007963
Gun cable 6 m - complete	1007964
Gun cable 12 m - complete	1007965
11 Rinsing air connection	1000804
11.1 Rinsing air hose was 100854 use 107066 rinse air tubing	107066.
12 Powder tube - complete	1007 958#
13 Compression spring	1001488
14 Clip ring	1007960
15 Hose connection Ø 11-12 mm - complete (incl. pos. 15.1)	1001340#
Hose connection Ø 9-10 mm - complete (incl. pos. 15.1)	1002030#
15.1 O ring for pos 15	1000822 #
16 Threaded sleeve (see corresponding Spare parts list)	
17 Nozzle (see corresponding Spare parts list)	
18 SuperCorona PC05	1008165#
19 Cascade space seal	1007635#